List of Required Data Entry Fields for Data Reported in the ERT

Note: Testites descended and the		Setup / Test Plan Module		
Note: Facility does not have to get test plan approved by the Agency, but ERT requires the test plan to be entered into the program before test results can be entered into the system.				
		Form: Facility/Tester		
Field Name	Field Optional or Required for ICR Test Request	Note:		
Facility Name	Required	Plant Name as reported in the Component 1 Reporting Tool.		
Address	Optional			
City	Optional			
State/Zip	Optional			
Address	Optional			
City	Optional			
State/Zip	Optional			
Contact	Optional			
Phone	Optional			
ax	Optional			
Email	Optional			
AFT Number	Optional			
ndustry NAICS	Optional			
RS	Optional			
Latitude	Optional			
Longitude	Optional			
Festing Company (TC)	Required			
C Address	Required			
fC City	Required			
C State/Zip	Required			
FC Contact	Required			
IC Phone	Required			
		Form: Permit/SCC		
		The code is the Facility ID provided in your the Section 114 letter and should be the same as the Facility ID		
Air Permit Number	Required	you entered for this facility in the Component 1 Reporting Tool.		
Permitted State Source ID/Name	Source ID-Required	Enter the unit ID that you provided for this unit in Component 1 and/or Component 2 of the ICR.		
	Name-Optional	The name is optional.		
The remainder of the Permit/SCC form	Optional	The remainder of this form, including the SCC section is optional.		
		Form: Regulations		
Question 1, 2, and 3	Optional			
		Form: Process/APCD		
		If required for your test, you should report the average heat input during the test run (mmBtu/hr); average fu composition and feed rate during each test run; and average steam output (1000 lb steam/hour) during each test run. If a control device is installed you must also report control device operating or monitoring paramete		
Duestion 4a Required	Required	If required for your test, you should report the average heat input during the test run (mmBtu/hr); average fur composition and feed rate during each test run; and average steam output (1000 lb steam/hour) during each test run. If a control device is installed you must also report control device operating or monitoring paramete during each test run (including, as appropriate to the control device, flue gas flow rate, pressure drop, scrubb liquor pH, scrubber liquor flow rate, sorbent type and sorbent injection rate), and process parameters (including, flue gas oxygen content (%), flue gas carbon dioxide content (%), flue gas moisture content (%), flue gas sampling point temperature (Deg F) and pressure (atm), standard temperature (Deg F) and pressure		
	Required	If required for your test, you should report the average heat input during the test run (mmBtu/hr); average fur composition and feed rate during each test run; and average steam output (1000 lb steam/hour) during each test run. If a control device is installed you must also report control device operating or monitoring paramete during each test run (including, as appropriate to the control device, flue gas flow rate, pressure drop, scrubb liquor pH, scrubber liquor flow rate, sorbent type and sorbent injection rate), and process parameters (including, flue gas oxygen content (%), flue gas carbon dioxide content (%), flue gas moisture content (%),		
Question 4b Required	Required Required Required Required	If required for your test, you should report the average heat input during the test run (mmBtu/hr); average fu composition and feed rate during each test run; and average steam output (1000 lb steam/hour) during each test run. If a control device is installed you must also report control device operating or monitoring paramete during each test run (including, as appropriate to the control device, flue gas flow rate, pressure drop, scrubb liquor pH, scrubber liquor flow rate, sorbent type and sorbent injection rate), and process parameters (including, flue gas oxygen content (%), flue gas carbon dioxide content (%), flue gas moisture content (%), flue gas sampling point temperature (Deg F) and pressure (atm), standard temperature (Deg F) and pressure		
Question 4a Required Question 4b Required Question 5a Required	Required	If required for your test, you should report the average heat input during the test run (mmBtu/hr); average fur composition and feed rate during each test run; and average steam output (1000 lb steam/hour) during each test run. If a control device is installed you must also report control device operating or monitoring paramete during each test run (including, as appropriate to the control device, flue gas flow rate, pressure drop, scrubb liquor pH, scrubber liquor flow rate, sorbent type and sorbent injection rate), and process parameters (including, flue gas oxygen content (%), flue gas carbon dioxide content (%), flue gas moisture content (%), flue gas sampling point temperature (Deg F) and pressure (atm), standard temperature (Deg F) and pressure (atm), unit gross electrical output (MWe), unit net electric generation (MWh)).		
Question 4b Required Question 5a Required	Required	If required for your test, you should report the average heat input during the test run (mmBtu/hr); average fur composition and feed rate during each test run; and average steam output (1000 lb steam/hour) during each test run. If a control device is installed you must also report control device operating or monitoring paramete during each test run (including, as appropriate to the control device, flue gas flow rate, pressure drop, scrubb liquor pH, scrubber liquor flow rate, sorbent type and sorbent injection rate), and process parameters (including, flue gas oxygen content (%), flue gas carbon dioxide content (%), flue gas moisture content (%), flue gas sampling point temperature (Deg F) and pressure (atm), standard temperature (Deg F) and pressure (atm), unit gross electrical output (MWe), unit net electric generation (MWh)). Listed below in Form: Attachments <i>Source/Process Flow Diagram</i> Required data entry fields for data reported in order of process flow. Add description and provide detailed description in section 5a. Each control device should have a target value, a unit of measure (UOM), and description in section 5a. Each control device should have a target value, a unit of measure (UOM), and description in section 5a. Each control device should have a target value, a unit of measure (UOM), and description in section 5a. Each control device should have a target value, a unit of measure (UOM), and description in section 5a. Each control device should have a target value, a unit of measure (UOM), and description of what the target value and the UOM represent. These values can be, for example, the guarantee emission limits or performance guarantee provided by control device vendors. Examples would be NO _x removal efficiency (in percent) for post combustion NO _x controls, PM removal efficiency (in percent) for PM		
Question 4b Required Question 5a Required	Required Required Required	If required for your test, you should report the average heat input during the test run (mmBtu/hr); average fur composition and feed rate during each test run; and average steam output (1000 lb steam/hour) during each test run. If a control device is installed you must also report control device operating or monitoring paramete during each test run (including, as appropriate to the control device, flue gas flow rate, pressure drop, scrubb liquor pH, scrubber liquor flow rate, sorbent type and sorbent injection rate), and process parameters (including, flue gas oxygen content (%), flue gas carbon dioxide content (%), flue gas moisture content (%), flue gas sampling point temperature (Deg F) and pressure (atm), standard temperature (Deg F) and pressure (atm), unit gross electrical output (MWe), unit net electric generation (MWh)). Listed below in Form: Attachments <i>Source/Process Flow Diagram</i> Required data entry fields for data reported in order of process flow. Add description and provide detailed description in section 5a. Each control device should have a target value, a unit of measure (UOM), and description of what the target value and the UOM represent. These values can be, for example, the guarantee emission limits or performance guarantee provided by control device vendors. Examples would be NO _x removal efficiency (in percent) for post combustion NO _x controls, PM removal efficiency (in percent) for PM controls, or SO ₂ removal efficiency in percent for post combustion SO ₂ controls. For example, for an ESP, a user might enter: in UOM (Percent), in Target (99), and in Comments (PM removal Efficiency).		
Question 4b Required Question 5a Required Question 5b Required Question 6	Required Required Required Required	If required for your test, you should report the average heat input during the test run (mmBtu/hr); average fur composition and feed rate during each test run; and average steam output (1000 lb steam/hour) during each test run. If a control device is installed you must also report control device operating or monitoring paramete during each test run (including, as appropriate to the control device, flue gas flow rate, pressure drop, scrubb liquor pH, scrubber liquor flow rate, sorbent type and sorbent injection rate), and process parameters (including, flue gas oxygen content (%), flue gas carbon dioxide content (%), flue gas moisture content (%), flue gas sampling point temperature (Deg F) and pressure (atm), standard temperature (Deg F) and pressure (atm), unit gross electrical output (MWe), unit net electric generation (MWh)). Listed below in Form: Attachments <i>Source/Process Flow Diagram</i> Required data entry fields for data reported in order of process flow. Add description and provide detailed description in section 5a. Each control device should have a target value, a unit of measure (UOM), and description of what the target value and the UOM represent. These values can be, for example, the guarantee emission limits or performance guarantee provided by control device vendors. Examples would be No _x removal efficiency (in percent) for post combustion NO _x controls, PM removal efficiency (in percent) for PM controls, or SO ₂ removal efficiency in percent for post combustion SO ₂ controls. For example, for an ESP, a user might enter: in UOM (Percent), in Target (99), and in Comments (PM removal Efficiency). Form: Locations/Methods		
Question 4b Required Question 5a Required Question 5b Required Question 6	Required Required Required	If required for your test, you should report the average heat input during the test run (mmBtu/hr); average fuc composition and feed rate during each test run; and average steam output (1000 lb steam/hour) during each test run. If a control device is installed you must also report control device operating or monitoring paramete during each test run (including, as appropriate to the control device, flue gas flow rate, pressure drop, scrubb liquor pH, scrubber liquor flow rate, sorbent type and sorbent injection rate), and process parameters (including, flue gas oxygen content (%), flue gas carbon dioxide content (%), flue gas moisture content (%), flue gas sampling point temperature (Deg F) and pressure (atm), standard temperature (Deg F) and pressure (atm), unit gross electrical output (MWe), unit net electric generation (MWh)). Listed below in Form: Attachments <i>Source/Process Flow Diagram</i> Required data entry fields for data reported in order of process flow. Add description and provide detailed description in section 5a. Each control device should have a target value, a unit of measure (UOM), and description of what the target value and the UOM represent. These values can be, for example, the guarantee emission limits or performance guarantee provided by control device vendors. Examples would be No _x removal efficiency (in percent) for post combustion NO _x controls, PM removal efficiency (in percent) for PM controls, or SO ₂ removal efficiency in percent for post combustion SO ₂ controls. For example, for an ESP, a user might enter: in UOM (Percent), in Target (99), and in Comments (PM removal Efficiency).		
Question 4b Required Question 5a Required Question 5b Required Question 6 Zuestion 6	Required Required Required Required	If required for your test, you should report the average heat input during the test run (mmBtu/hr); average fur composition and feed rate during each test run; and average steam output (1000 lb steam/hour) during each test run. If a control device is installed you must also report control device operating or monitoring paramete during each test run (including, as appropriate to the control device, flue gas flow rate, pressure drop, scrubb liquor pH, scrubber liquor flow rate, sorbent type and sorbent injection rate), and process parameters (including, flue gas sampling point temperature (Dg F) and pressure (atm), standard temperature (Deg F) and pressure (atm), standard temperature (Deg F) and pressure (atm), standard temperature (Deg F) and pressure (atm), unit gross electrical output (MWe), unit net electric generation (MWh)). Listed below in Form: Attachments <i>Source/Process Flow Diagram</i> Required data entry fields for data reported in order of process flow. Add description and provide detailed description in section 5a. Each control device should have a target value, a unit of measure (UOM), and description of what the target value and the UOM represent. These values can be, for examples would be NO _x removal efficiency (in percent) for post combustion NO _x controls, PM removal efficiency (in percent) for PN controls, or SO ₂ removal efficiency in percent for post combustion SO ₂ controls. For example, for an ESP, a user might enter: in UOM (Percent), in Target (99), and in Comments (PM removal Efficiency). Form: Locations/Methods Location of test should be downstream from the last control device. Each test should be at least comprised of three runs. The units of measure for each method should match the units provided in the instructions included in Component 4.		
Question 4b Required Question 5a Required Question 5b Required Question 6 7a	Required	If required for your test, you should report the average heat input during the test run (mmBtu/hr); average fuc composition and feed rate during each test run; and average steam output (1000 lb steam/hour) during each test run. If a control device is installed you must also report control device operating or monitoring paramete during each test run (including, as appropriate to the control device, flue gas flow rate, pressure drop, scrubb liquor PH, scrubber liquor flow rate, sorbent type and sorbent injection rate), and process parameters (including, flue gas oxygen content (%), flue gas carbon dioxide content (%), flue gas moisture content (%), flue gas sampling point temperature (Deg F) and pressure (atm), standard temperature (Deg F) and pressure (atm), unit gross electrical output (MWe), unit net electric generation (MWh)). Listed below in Form: Attachments <i>Source/Process Flow Diagram</i>		
Question 4b Required Question 5a Required Question 5b Required Question 6 7a	Required Required Required Required Required Required	If required for your test, you should report the average heat input during the test run (mmBtu/hr); average fur composition and feed rate during each test run; and average steam output (1000 lb steam/hour) during each test run. If a control device is installed you must also report control device operating or monitoring paramete during each test run (including, as appropriate to the control device, flue gas flow rate, pressure drop, scrubb liquor pH, scrubber liquor flow rate, sorbent type and sorbent injection rate), and process parameters (including, flue gas oxygen content (%), flue gas carbon dioxide content (%), flue gas moisture content (%), flue gas sampling point temperature (Deg F) and pressure (atm), standard temperature (Deg F) and pressure (atm), unit gross electrical output (MWe), unit net electric generation (MWh)). Listed below in Form: Attachments <i>Source/Process Flow Diagram</i> Required data entry fields for data reported in order of process flow. Add description and provide detailed description in section 5a. Each control device should have a target value, a unit of measure (UOM), and description of what the target value and the UOM represent. These values can be, for example, the guarantee emission limits or performance guarantee provided by control device vendors. Examples would be NO _x removal efficiency (in percent) for post combustion NO _x controls, PM removal efficiency (in percent) for PM controls, or SO ₂ removal efficiency in percent for post combustion SO ₂ controls. For example, for an ESP, a user might enter: in UOM (Percent), in Target (99), and in Comments (PM removal Efficiency). Form: Locations/Methods Location of test should be downstream from the last control device. Each test should be at least comprised of three runs. The units of measure for each method should match the units provided in the instructions included in Component 4. Form: Methods Cont.		
Question 4b Required Question 5a Required Question 5b Required Question 6 7a 7b Questions 8-11	Required	If required for your test, you should report the average heat input during the test run (mmBtu/hr); average fur composition and feed rate during each test run; and average steam output (1000 lb steam/hour) during each test run. If a control device is installed you must also report control device operating or monitoring paramete during each test run (including, as appropriate to the control device, flue gas flow rate, pressure drop, scrubb liquor pH, scrubber liquor flow rate, sorbent type and sorbent injection rate), and process parameters (including, flue gas sampling point temperature (Dg F) and pressure (atm), standard temperature (Deg F) and pressure (atm), standard temperature (Deg F) and pressure (atm), standard temperature (Deg F) and pressure (atm), unit gross electrical output (MWe), unit net electric generation (MWh)). Listed below in Form: Attachments <i>Source/Process Flow Diagram</i> Required data entry fields for data reported in order of process flow. Add description and provide detailed description in section 5a. Each control device should have a target value, a unit of measure (UOM), and description of what the target value and the UOM represent. These values can be, for examples would be NO _x removal efficiency (in percent) for post combustion NO _x controls, PM removal efficiency (in percent) for PN controls, or SO ₂ removal efficiency in percent for post combustion SO ₂ controls. For example, for an ESP, a user might enter: in UOM (Percent), in Target (99), and in Comments (PM removal Efficiency). Form: Locations/Methods Location of test should be downstream from the last control device. Each test should be at least comprised of three runs. The units of measure for each method should match the units provided in the instructions included in Component 4.		
Question 4b Required	Required	If required for your test, you should report the average heat input during the test run (mmBtu/hr); average fur composition and feed rate during each test run; and average steam output (1000 lb steam/hour) during each test run. If a control device is installed you must also report control device operating or monitoring paramete during each test run (including, as appropriate to the control device, flue gas flow rate, pressure drop, scrubb liquor pH, scrubber liquor flow rate, sorbent type and sorbent injection rate), and process parameters (including, flue gas oxygen content (%), flue gas carbon dioxide content (%), flue gas moisture content (%), flue gas sampling point temperature (Deg F) and pressure (atm), standard temperature (Deg F) and pressure (atm), unit gross electrical output (MWe), unit net electric generation (MWh)). Listed below in Form: Attachments <i>Source/Process Flow Diagram</i> Required data entry fields for data reported in order of process flow. Add description and provide detailed description in section 5a. Each control device should have a target value, a unit of measure (UOM), and description of what the target value and the UOM represent. These values can be, for example, the guarantee emission limits or performance guarantee provided by control device vendors. Examples would be No _x removal efficiency (in percent) for post combustion NO _x controls, PM removal efficiency). Form: Locations/Methods Location of test should be downstream from the last control device. Each test should be at least comprised of three runs. The units of measure for each method should match the units provided in the instructions included in Component 4. Form: Methods Cont. Form: Methods Cont.		
Question 4b Required Question 5a Required Question 5b Required Question 6 7a 7b Questions 8-11 Questions 12-16	Required Required	If required for your test, you should report the average heat input during the test run (mmBtu/hr); average fur composition and feed rate during each test run; and average steam output (1000 lb steam/hour) during each test run. If a control device is installed you must also report control device operating or monitoring paramete during each test run (including, as appropriate to the control device, flue gas flow rate, pressure drop, scrubb liquor pH, scrubber liquor flow rate, sorbent type and sorbent injection rate), and process parameters (including, flue gas oxygen content (%), flue gas carbon dioxide content (%), flue gas moisture content (%), flue gas sampling point temperature (Deg F) and pressure (atm), standard temperature (Deg F) and pressure (atm), unit gross electrical output (MWe), unit net electric generation (MWh)). Listed below in Form: Attachments <i>Source/Process Flow Diagram</i> Required data entry fields for data reported in order of process flow. Add description and provide detailed description in section 5a. Each control device should have a target value, a unit of measure (UOM), and description of what the target value and the UOM represent. These values can be, for example, the guarantee emission limits or performance guarantee provided by control device vendors. Examples would be NO _x removal efficiency (in percent) for post combustion NO _x controls, PM removal efficiency (in percent) for PM controls, or SO ₂ removal efficiency in percent for post combustion SO ₂ controls. For example, for an ESP, a user might enter: in UOM (Percent), in Target (99), and in Comments (PM removal Efficiency). Form: Locations/Methods Location of test should be downstream from the last control device. Each test should be at least comprised of three runs. The units of measure for each method should match the units provided in the instructions included in Component 4. Form: Methods Cont.		
Question 4b Required Question 5a Required Question 5b Required Question 6 7a 7b Questions 8-11	Required	If required for your test, you should report the average heat input during the test run (mmBtu/hr); average fu composition and feed rate during each test run; and average steam output (1000 lb steam/hour) during each test run. If a control device is installed you must also report control device operating or monitoring paramete during each test run (including, as appropriate to the control device, flue gas flow rate, pressure drop, scrubbl liquor pH, scrubber liquor flow rate, sorbent type and sorbent injection rate), and process parameters (including, flue gas oxygen content (%), flue gas carbon dioxide content (%), flue gas moisture content (%), flue gas sampling point temperature (Deg F) and pressure (atm), standard temperature (Deg F) and pressure (atm), unit gross electrical output (MWe), unit net electric generation (MWh)). Listed below in Form: Attachments <i>Source/Process Flow Diagram</i> Required data entry fields for data reported in order of process flow. Add description and provide detailed description in section 5a. Each control device should have a target value, a unit of measure (UOM), and description of what the target value and the UOM represent. These values can be, for example, the guarantee emission limits or performance guarantee provided by control device vendors. Examples would be No removal efficiency (in percent) for post combustion NO, controls, PM removal efficiency (in percent) for PM controls, or SO ₂ removal efficiency in percent for post combustion SO ₂ controls. For example, for an ESP, a user might enter: in UOM (Percent), in Target (99), and in Comments (PM removal Efficiency). Form: Locations/Methods Location of test should be downstream from the last control device. Each test should be at least comprised of three runs. The units of measure for each method should match the units provided in the instructions included in Component 4. Form: Methods Cont. Form: Methods Cont.		
Question 4b Required Question 5a Required Question 5b Required Question 6 7a 7b Questions 8-11 Questions 12-16	Required Required	If required for your test, you should report the average heat input during the test run (mmBtu/hr); average fur composition and feed rate during each test run; and average steam output (1000 lb steam/hour) during each test run. If a control device is installed you must also report control device operating or monitoring paramete during each test run (including, as appropriate to the control device, flue gas flow rate, pressure drop, scrubb liquor pH, scrubber liquor flow rate, sorbent type and sorbent injection rate), and process parameters (including, flue gas oxygen content (%), flue gas carbon dioxide content (%), flue gas moisture content (%), flue gas sampling point temperature (Deg F) and pressure (atm), standard temperature (Deg F) and pressure (atm), unit gross electrical output (MWe), unit net electric generation (MWh)). Listed below in Form: Attachments <i>Source/Process Flow Diagram</i> Required data entry fields for data reported in order of process flow. Add description and provide detailed description in section 5a. Each control device should have a target value, a unit of measure (UOM), and description of what the target value and the UOM represent. These values can be, for example, the guarantee emission limits or performance guarantee provided by control device vendors. Examples would be No _x removal efficiency (in percent) for post combustion NO _x controls, PM removal efficiency). Form: Locations/Methods Location of test should be downstream from the last control device. Each test should be at least comprised of three runs. The units of measure for each method should match the units provided in the instructions included in Component 4. Form: Methods Cont. Form: Methods Cont.		

Test Data Module			
All Questions	Required		
Form: Attachments			
Source/Process Flow Diagram			
Alternate Method Request and Approval (Item 8) (optional)			
EPA Method 1Location Supporting Documentation (Item 9) (optional)		Rather than attaching the these items to the ERT, they should be included in the test report submitted to the Refinery ICR website or to the ICR email address.	
Cyclonic Flow Absence Supporting Documentation (Item 10)			
Pre-Test Meter Boxes/DGMs Calibrations			
Post-Test Meter Boxes/DGMs Calibrations			
Nozzles Calibrations			
Pitots Calibrations			
Thermocouples Calibrations			
Sampling Locations Dimensions and Point Locations			
Run Field Data Sheets			
Moisture Recovery			
Lab Data including calibrations and detection level determinations			
Chain-of-Custody			
Observer Comments			
APCD Diagram			
Test Data Review Module			
All Questions	Required		
Test Report Module			
All Questions for Report Signatures Form	Required		