



U.S. Department of the Interior
Office of Surface Mining Reclamation and Enforcement
e-AMLIS Report

Date Prepared: **2/27/2013**Prepared By: **Marcia Murdock**Phone: **(307) 335-6946**Last Modified: **2/28/2013**

Field Contact:

Phone:

AMLIS Key: **WY072868**PA Name: **McCann Pass #1**PU Name: **GLENDO RESERVOIR**PU Number: **019**Latitude: **42.37383**Longitude: **-104.63328**State/Tribe: **Wyoming**County: **GOSHEN**Cong Dist: **1**FIPS Code: **56015**Watershed: **GLENDO RESERVOIR**HUC Code: **10180008**Quadrangle: **GUERNSEY**Mining Type: **U**Surface Owners: **Private 100%**Ore Types: **O**

Problem Summary

Problem	Unfunded		Funded		Completed		Total		
	Prio/Type/Fund	Units	Costs	Units	Costs	Units	Costs	Units	Costs
2 P NH2		0	0.00	0	0.00	1	13,189.00	1	13,189.00

Priority Totals

P1 Total	-	0.00	-	0.00	-	0.00	-	0.00
P2 Total	-	0.00	-	0.00	-	13,189.00	-	13,189.00
P3 Total	-	0.00	-	0.00	-	0.00	-	0.00
PAD Total	-	0.00	-	0.00	-	13,189.00	-	13,189.00