


The following image illustrates the summary for NPA airspace with SA ON and no barometric aiding (refer to Figure 10-3, RAIM Summary — NPA Airspace, with SA On and No Baro-aiding).

Displaying TSO-C129, no barometric aiding, RAIM NPA airspace,
Selective Availability ON, mask angle: 5.0°

Outage Summaries available for 2018/05/03 22:42 - 2018/05/06 21:42
UTC



[Click here](#) to see an interactive version of this.